

Manufacturer's name: Finder SpA

Manufacturer's address: Via Drubiaglio 14
10040
Almese (TO)
Italy

Declares under sole responsibility that the product as originally delivered:

Product: 93 Series - 93.21 / 93.68 / 93.69 Types: Timer Sockets for 34 Series Relays

Authorised Representative's name: Finder plc

Authorised Representative's address: Opal Way
Stone Business Park
Stone,
Staffordshire
ST15 0SS
UK

Complies with the following statutory requirements and carries the UKCA mark accordingly	By conforming to the following designated standards.
Electrical Equipment (Safety) Regulations 2016 No.1101 [as amended]	BS EN 61812-1:2011*
Electromagnetic Compatibility Regulations 2016 No.1091 [as amended]	BS EN 61812-1:2011**
Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 No.3032 [as amended]	BS EN IEC 63000:2018

*ds-low-voltage-equipment-list-v05

**ds-emc-list-v03

Signed for and on behalf of:	Finder SpA
Issued at:	Almese (TO) Italy
Date:	27/Feb/2023
Name:	Marcello Grande
Function:	Technical Manager
Signature:	